

KDC 200 Reset and Configure Windows

Initial Situation

The KDC200 no longer functions as expected. The connection is only established sporadically or the scanned barcodes are no longer transferred.


Solution

Reset the scanner to factory settings and set it up again.

1. Exit DeDeSales completely and Disable Bluetooth on the PC

1.1 To Disable Bluetooth, press the Windows key + A and click on the Bluetooth icon.

1. Scan the following barcodes one after the other. Pay attention to the scanner and only scan the next barcode when the green status LED goes out.



Save if Not Sent



82004

Enable Auto Power On



66001

Enable Auto Power Off



64001

1. Enable Bluetooth again by pressing Windows key + A and clicking on the Bluetooth icon, then Start DeDeSales.
2. The scanner now works as usual again.

Revision #7

Created 2026-08-31 10:38:21 UTC by n8n

Updated 2026-09-02 15:04:31 UTC by n8n